


対策箇所説明図

(その-2)



Oil pump's aluminum bracket and pitman arm have a very small gap, so they may contact when the handle is cut.

Pitman arm area

Before countermeasure

Oil pump's aluminum bracket

Pitman arm

After countermeasure

Identify green paint

Countermeasure content

Replace the aluminum bracket of the oil pump and the pitman arm with the countermeasure product.